

Er.B.M.Gupta
E.E. CPWD (Retd)
Consultant Engineer

(M) 9818992427
9213317917

Dated 16.12.2016

To,

The Principal
Kendriya Vidyalaya
Masjid Moth
Sec-03, Sadiq Nagar
New Delhi -110 049

Subject :- Safety & Security Certificate of School Building of KV Masjid Moth Sadiq Nagar Sec-03, New Delhi-110049

Ref. :- Your letter F.18/KVMM/2016-17 dated 12.12.2016

Sir,

With reference to the above cited letter I was asked to inspect the school building and assess the safety and security of the same.


The school bldg was inspected alongwith you on 16.12.2016 to assess the safety & security aspect of the building.

It is certified that the school building is structurally safe and sound and no apparent/visible. Cracks or Deformation was detected in the building at the time of inspection on 16.12.2016.

No major work is suggested at this stage accept covering of Expansion Joints of the building

The report is submitted for taking up appropriate action at your end please.

Yours Sincerely


(Er. B.M.Gupta) 16/12/16

Consultant Engineer
ER. B.M. GUPTA
Consultant Engineer
E.E., CPWD (Retd.),
G-1A/124-A Janak Puri